

INDIANA DEPARTMENT OF HOMELAND SECURITY CODE SERVICES SECTION 302 West Washington Street, Room W246

302 West Washington Street, Room W246 Indianapolis, IN 46204-2739



INSTRUCTIONS: Please refer to the attached four (4) page instructions. Variance number (Assigned by department) Attach additional pages as needed to complete this application. 16-12-05 1. APPLICANT INFORMATION (Person who would be in violation if variance is not granted; usually this is the owner) Name of applicant Sinergy Investments, LLC Owner Name of organization Telephone number Sinergy Investments, LLC (812) 426-1070 Address (number and street, city, state, and ZIP code) 420 NW 5th Street, Ste 202, Evansville, IN 47708 2. PERSON SUBMITTING APPLICATION ON BEHALF OF THE APPLICANT (If not submitted by the applicant) Name of applicant Jan Meeks **Property Management Company** Name of organization Telephone number Summit Real Estate Services (812) 426 1070 Address (number and street, city, state, and ZIP code) 420 NW 5th Street, Evansville, IN 47708 3. DESIGN PROFESSIONAL OF RECORD (If applicable) Name of design professional License number Name of organization Telephone number Address (number and street, city, state, and ZIP code) 4. PROJECT IDENTIFICATION Name of project State project number County West Broadway Shopping Center 379334 Gibson Address of site (number and street, city, state, and ZIP code) 1543 W. Broadway St., Princeton, IN 47670 Type of project ☐ New Addition ☐ Alteration ☐ Change of occupancy Existing 5. REQUIRED ADDITIONAL INFORMATION The following required information has been included with this application (check as applicable): A check made payable to the Indiana Department of Homeland Security for the appropriate amount. (see instructions) One (1) set of plans or drawings and supporting data that describe the area affected by the requested variance and any proposed alternatives. Written documentation showing that the local fire official has received a copy of the variance application. Written documentation showing that the local building official has received a copy of the variance application. 6. VIOLATION INFORMATION Has the Plan Review Section of the Division of Fire and Building Safety issued a Correction Order? Yes (If yes, attach a copy of the Correction Order.) Has a violation been issued? Yes (If yes, attach a copy of the Violation and answer the following.) Violation issued by: Local Building Department State Fire and Building Code Enforcement Section Local Fire Department

7.	7. DESCRIPTION OF REQUESTED VARIANCE				
Nai	ne of code or standard and edition involved	Specific code section			
10	14.2 Egress through intervening spaces	2.4.			
Eg	ore of non-compliance (Include a description of spaces, equipment, etc. in ress through non-customer area, stock rooms, storage are	volved as necessary.) 38	<u> </u>		
ļ					
8.	DEMONSTRATION THAT PUBLIC HEALTH, SAFETY, AND WE	ELFARE WILL BE PROTECTED			
Sel	ect one of the following statements:				
×	Non-compliance with the rule will not be adverse to the public h	ealth, safety or welfare; or			
Ø					
Fac In S	s demonstrating that the above selected statement is true: Sears, Dollar General and Finders Keepers the rear exit is the retail husinesses	through a pap quetomor over the			
for	the retail businesses.	anough a non-content area o	iat is used as a stock room, storage area		
Ар	roposed path of exit would be painted on the floor, clearly	defining the path of exit at a min	pirmum of \$4" wide convince the room and for		
Sea	ers, Dollar General and Finders Keepers, as previously no	ted during the 8-5-16 inspection	remain or 44 Mide serving the test exit for		
Sele	DEMONSTRATION OF UNDUE HARDSHIP OR HISTORICALLY ct at least one of the following statements;	SIGNIFICANT STRUCTURE			
		difficultied by a payment of a tour boat Park out	••		
☒	imposition of the rule would result in an undue hardehin (unusual	difficulty) because of physical limitation	ons of the construction site or its utility services.		
☒	imposition of the rule would result in an undue hardship (unusual of Imposition of the rule would result in an undue hardship (unusual)	difficulty) because of major operation	al problems in the use of the building or structure.		
	Imposition of the rule would result in an undue hardship (unusual a Imposition of the rule would prevent the preservation of an architecture)	ounculty) because of excessive costs	of additional or altered construction elements.		
Facis	demonstrating that the above selected statement is tour				
ne	installation of bollards/posts and chains will create an unc	due hardship on the retail users	of the space making the movement of		
stock from one side of the space to the other very difficult as large carts or lifts are used to move the large and small stock items. The location of the boliards in effect divides the space in the middle meaning all merchandise movement will need to pass through the					
corridor multiple times during the normal business day.					
This will also create a financial hardship on the merchants in that the installation of the bollards and chains it will require many more					
hours of labor to navigate around the posts to avoid hitting and potentially damaging the posts and merchandise.					
10 STATEMENT OF ACCUMAN					
10. STATEMENT OF ACCURACY					
I hereby certify under penalty of perjury that the information contained in this application is accurate.					
Sign	ture of applicant or person submitting application	Please print name	Date of signature (month, day, year)		
Sidol		Jan Meeks	11/3/2016		
- Jan	tore or cestifu horiesarcusi (u abbicatrie)	Please print name	Date of signature (month, day, year)		
11.	STATEMENT OF AWARENESS (If the application is submitted	for the anglicant's behalf above			
	I hereby certify under penalty of perjury that I am aware of this request for variance and that this application is being submitted on my behalf.				
Signa	ture of applicant F	Please print name	Date of signature (gnonth, day, year)		
	_ V	Enrique Covarnibias	11/2/2016		



FIRE AND BUILDING **CODE ENFORCEMENT INSPECTION REPORT ORDER**

DIVISION OF FIRE AND BUILDING SAFETY INDIANA DEPARTMENT OF HOMELAND SECURITY 302 WEST WASHINGTON STREET, RM E241 INDIANAPOLIS, IN 46204 TELEPHONE: 317-232-2222

WEB ADDRESS: WWW.IN.GOV/DHS

Identification Number	Name of the facil	ity	A CONTRACTOR OF THE CONTRACTOR	County
379334	WEST BROADWA	Y SHOPPING CEN	TER	GIBSON
Address of Property			Name of the Contact	Telephone Number
1543 W BROADWAY ST F	PRINCETON 47670		JUDY BEEM-PROPERTY MANAGER/ENRIQU	(812) 454-8904
Email	<u> </u>			Inspection Date
beem@summitrealestate	e.us			08/05/2016
nspection Category		Inspection Type	Inspection Status	<u> </u>
CONSTRUCTION DESIGN	I RELEASE	INITIAL	VIOLATION	
Name of the inspector	RYAN WINEINGE	R	Phone: 3174176650	
Email: rwineinger@dhs.ii	n.gov			

Violations

VIO- CLATION	RULE OR INDIANA CODE SECTION VIOLATED	DESCRIPTION OF VIOLATION	DATE BY WHICH VIOLATION MUST BE CORRECTED
20	Sec. 1014.2 014 Edition IBC 75 IAC 13-2.6	Egress through intervening spaces shall comply with this section. 1. Egress from a room or space shall not pass through adjoining or intervening rooms or areas, except where such adjoining rooms or areas and the area served are accessory to one or the other, are not a Group H occupancy and provide a discernible path of egress travel to an exit. Exception: Means of egress are not prohibited through adjoining or intervening rooms or spaces in a Group H, S or F occupancy when the adjoining or intervening rooms or spaces are the same or a lesser hazard occupancy group. 2. An exit access shall not pass through a room that can be locked to prevent egress. 3. Means of egress from dwelling units or sleeping areas shall not lead through other sleeping areas, toilet rooms or bathrooms. 4. Egress shall not pass through kitchens, storage rooms, closets or spaces used for similar purposes. Exceptions: 1. Means of egress are not prohibited through a kitchen area serving adjoining rooms constituting part of the same dwelling unit or sleeping unit. 2. Means of egress are not prohibited through stockrooms in Group M occupancies when all of the following are met: 2.1. The stock is of the same hazard classification as that found in the main retail area; 2.2. Not more than 50 percent of the exit access is through the stockroom; 2.3. The stockroom is not subject to locking from the egress side; and 2.4. There is a demarcated, minimum 44-inch-wide (1118 mm) aisle defined by full- or partial-height fixed walls or similar construction that will maintain the required width and lead directly from the retail area to the exit without obstructions. A wall or similar construction have not been installed in the Sears, Dollar General, and Finders Keepers stock rooms, to meet condition	09/05/2016

Automatic sprinklers shall be installed with due regard to obstructions that will delay activation or obstruct the water distribution pattern. Automatic sprinklers shall be installed in or under covered klosks, displays, booths, concession stands, or equipment that exceeds 4 feet (1219 mm) in width. Not less than a 3-foot (914 mm) clearance shall be maintained between automatic sprinklers and the top of piles of combustible fibers. Exception: Kitchen equipment under exhaust hoods protected with a fire-extinguishing system in accordance with Section 904. The rear exit corridor located in the Sears stock room is not being provided with appropriate explaints accordance.	09/05/2016
There shall be a floor or landing on each side of a door. Such floor or landing shall be at the same elevation on each side of the door. Landings shall be level except for exterior landings, which are permitted to have a slope not to exceed 0.25 unit vertical in 12 units horizontal (2-percent slope). Exceptions: 1. Doors serving individual dwelling units in Groups R-2 and R-3 where the following apply: 1.1. A door is permitted to open at the top step of an interior flight of stairs, provided the door does not swing over the top step. 1.2. Screen doors and storm doors are permitted to swing over stairs or landings. 2. Exterior doors as provided for in Section 1003.5, Exception 1, and Section 1020.2, which are not on an accessible route. 3. In Group R-3 occupancies not required to be Accessible units, Type A units or Type B units, the landing at an exterior doorway shall not be more than 7 3/4 inches (197 mm) below the top of the threshold, provided the door, other than an exterior storm or screen door, does not swing over the landing. 4. Variations in elevation due to differences in finish materials, but not more than 1/2 inch (12.7 mm). 5. Exterior decks, patios or balconies that are part of Type B dwelling units, have impervious surfaces and that are not more than 4 inches (102 mm) below the finished floor level of the adjacent interior space of the dwelling unit.	09/05/2016
	that will delay activation or obstruct the water distribution pattern. Automatic sprinklers shall be installed in or under covered kiosks, displays, booths, concession stands, or equipment that exceeds 4 feet (1219 mm) in width. Not less than a 3-foot (914 mm) clearance shall be maintained between automatic sprinklers and the top of piles of combustible fibers. Exception: Kitchen equipment under exhaust hoods protected with a fire-extinguishing system in accordance with Section 904. The rear exit corridor located in the Sears stock room is not being provided with appropriate sprinkler coverage. There shall be a floor or landing on each side of a door. Such floor or landing shall be at the same elevation on each side of the door. Landings shall be level except for exterior landings, which are permitted to have a slope not to exceed 0.25 unit vertical in 12 units horizontal (2-percent slope). Exceptions: 1. Doors serving individual dwelling units in Groups R-2 and R-3 where the following apply: 1.1. A door is permitted to open at the top step of an interior flight of stairs, provided the door does not swing over the top step. 1.2. Screen doors and storm doors are permitted to swing over stairs or landings. 2. Exterior doors as provided for in Section 1003.5, Exception 1, and Section 1020.2, which are not on an accessible route. 3. In Group R-3 occupancies not required to be Accessible units, Type A units or Type B units, the landing at an exterior doorway shall not be more than 7.3/4 inches (197 mm) below the top of the threshold, provided fine door, other than an exterior storm or screen door, does not swing over the landing. 4. Variations in elevation due to differences in finish materials, but not more than 1/2 inch (12.7 mm). 5. Exterior decks, paties or balconies that are part of Type B dwelling units, have impervious surfaces and that are not more than 4 inches (102 mm) below the finished floor level of the adjacent interior space

Inspection Notes:

A site visit was made to meet with the new owner and property management company. I was accompanied by Judy Beem and Tyler Raben of Summit Real Estate Services, who are serving as the property manager, and owner Enrique Covarrudias. I showed them the areas where violations still exist and explained why they were violations. I spoke with project Design Professional Thomas Blyth who stated it was okay for the new owner to contact him to obtain the already completed plans and filing information.

Facility Id	Received By Name	Signature and Date	
379334	•		